

FIRE SAFETY REPORT

Emergency Response

Boston University has 24-hour dispatch centers for Facilities Management and for Police/Public Safety at each of its campuses. These dispatch centers utilize a number of communication protocols to activate emergency plans, notify appropriate responders, and then escalate or de-escalate that response as appropriate.

In the event of a fire, call 911 first.

Facilities Management emergency response:

- **Charles River Campus—617-353-2105; Medical Campus—617-638-4144**

Police/Public Safety emergency response:

- **Charles River Campus—617-353-2121; Medical Campus—617-414-4444**

Fires at Boston University are handled by appropriately trained responders only. Residents are trained to activate the fire alarm and evacuate. The first responders from Environment Health & Safety, Facilities, and/or BUPD are responsible for managing a safe response, a controlled environment, interaction with the responding fire department, and recovery and reoccupation when the incident is resolved.



FIRE STATISTICS

The following reflects fire statistics for calendar years 2010, 2011, and 2012. For more information, please visit www.bu.edu/firesafety or www.bu.edu/ehs/programs/safety-and-health/fire-safety.

BOSTON UNIVERSITY ON-CAMPUS RESIDENTIAL FIRE REPORT

Address	Fires Reported			Date Occurred			Cause			Number of Injuries that Required Treatment at a Medical Facility			Number of Fire-Related Deaths			Value of Property Damage		
	2010	2011	2012	2010	2011	2012	2010	2011	2012	2010	2011	2012	2010	2011	2012	2010	2011	2012
273 Babcock St	2	0	0	10/22/10			arson				0	0	0	0	0	\$812.00	\$-	\$-
				11/20/10			open flame				0	0	0	0	0	\$15.00	\$-	\$-
275 Babcock St	0	0	0								0	0	0	0	0	\$-	\$-	\$-
277 Babcock St	0	0	1			01/28/12			unknown		0	0	0	0	0	\$-	\$-	\$150.00
11 Bay State Rd	0	0	0								0	0	0	0	0	\$-	\$-	\$-
30 Bay State Rd	0	0	0								0	0	0	0	0	\$-	\$-	\$-
56 Bay State Rd	0	0	0								0	0	0	0	0	\$-	\$-	\$-
58 Bay State Rd	0	0	0								0	0	0	0	0	\$-	\$-	\$-
59 Bay State Rd	0	0	0								0	0	0	0	0	\$-	\$-	\$-
60 Bay State Rd	0	0	0								0	0	0	0	0	\$-	\$-	\$-
61 Bay State Rd	0	0	0								0	0	0	0	0	\$-	\$-	\$-
62 Bay State Rd	0	0	0								0	0	0	0	0	\$-	\$-	\$-
65 Bay State Rd	0	0	0								0	0	0	0	0	\$-	\$-	\$-
68 Bay State Rd	0	0	0								0	0	0	0	0	\$-	\$-	\$-
69 Bay State Rd	0	0	0								0	0	0	0	0	\$-	\$-	\$-
70 Bay State Rd	0	0	0								0	0	0	0	0	\$-	\$-	\$-
71 Bay State Rd	0	0	0								0	0	0	0	0	\$-	\$-	\$-
74 Bay State Rd	0	0	0								0	0	0	0	0	\$-	\$-	\$-
75 Bay State Rd	0	0	0								0	0	0	0	0	\$-	\$-	\$-
76 Bay State Rd	0	0	0								0	0	0	0	0	\$-	\$-	\$-
77 Bay State Rd	0	0	0								0	0	0	0	0	\$-	\$-	\$-
78 Bay State Rd	0	0	0								0	0	0	0	0	\$-	\$-	\$-
79 Bay State Rd	0	0	0								0	0	0	0	0	\$-	\$-	\$-
80 Bay State Rd	0	0	0								0	0	0	0	0	\$-	\$-	\$-

Address	Fires Reported			Date Occurred			Cause			Number of Injuries that Required Treatment at a Medical Facility			Number of Fire-Related Deaths			Value of Property Damage			
	2010	2011	2012	2010	2011	2012	2010	2011	2012	2010	2011	2012	2010	2011	2012	2010	2011	2012	
81 Bay State Rd	0	0	0										0	0	0	0	0	0	\$-
82 Bay State Rd	0	1	0		03/10/11			cooking					0	0	0	0	0	0	\$315.00
83 Bay State Rd	0	0	0										0	0	0	0	0	0	\$-
84 Bay State Rd	0	0	0										0	0	0	0	0	0	\$-
86 Bay State Rd	0	0	0										0	0	0	0	0	0	\$-
88 Bay State Rd	0	0	0										0	0	0	0	0	0	\$-
90 Bay State Rd	0	0	0										0	0	0	0	0	0	\$-
91 Bay State Rd	0	0	0										0	0	0	0	0	0	\$-
92 Bay State Rd	0	0	0										0	0	0	0	0	0	\$-
94 Bay State Rd	0	0	0										0	0	0	0	0	0	\$-
96 Bay State Rd	0	0	0										0	0	0	0	0	0	\$-
110 Bay State Rd	0	0	0										0	0	0	0	0	0	\$-
112 Bay State Rd	0	0	0										0	0	0	0	0	0	\$-
113 Bay State Rd	0	0	0										0	0	0	0	0	0	\$-
115 Bay State Rd	0	0	0										0	0	0	0	0	0	\$-
117 Bay State Rd	0	0	0										0	0	0	0	0	0	\$-
124 Bay State Rd	0	0	0										0	0	0	0	0	0	\$-
131 Bay State Rd	0	0	0										0	0	0	0	0	0	\$-
133 Bay State Rd	0	0	0										0	0	0	0	0	0	\$-
135 Bay State Rd	0	0	0										0	0	0	0	0	0	\$-
139 Bay State Rd	0	0	1		05/10/12							cooking	0	0	0	0	0	0	\$500.00
140 Bay State Rd	1	0	0				08/29/10			open flame			1	0	0	0	0	0	n/a
153 Bay State Rd	0	0	0										0	0	0	0	0	0	\$-
157 Bay State Rd	0	0	0										0	0	0	0	0	0	\$-
158 Bay State Rd	0	0	0										0	0	0	0	0	0	\$-
159 Bay State Rd	0	0	0										0	0	0	0	0	0	\$-
160 Bay State Rd	0	0	0										0	0	0	0	0	0	\$-
161 Bay State Rd	0	0	0										0	0	0	0	0	0	\$-
162 Bay State Rd	0	0	0										0	0	0	0	0	0	\$-
163 Bay State Rd	0	0	0										0	0	0	0	0	0	\$-
164 Bay State Rd	0	0	0										0	0	0	0	0	0	\$-
166 Bay State Rd	0	0	0										0	0	0	0	0	0	\$-

Address	Fires Reported			Date Occurred			Cause			Number of Injuries that Required Treatment at a Medical Facility			Number of Fire-Related Deaths			Value of Property Damage						
	2010	2011	2012	2010	2011	2012	2010	2011	2012	2010	2011	2012	2010	2011	2012	2010	2011	2012				
167 Bay State Rd	0	0	0										0	0	0	0	0	0	\$-	\$-	\$-	
168 Bay State Rd	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
169 Bay State Rd	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
171 Bay State Rd	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
172 Bay State Rd	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
173 Bay State Rd	0	0	1			08/27/12						cooking	0	0	0	0	0	0	0	\$-	\$-	\$349.00
175 Bay State Rd	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
176 Bay State Rd	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
177 Bay State Rd	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
178 Bay State Rd	0	0	1			05/08/12						cooking	0	0	0	0	0	0	0	\$-	\$-	\$349.00
179 Bay State Rd	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
180 Bay State Rd	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
181 Bay State Rd	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
182 Bay State Rd	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
183 Bay State Rd	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
184 Bay State Rd	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
186 Bay State Rd	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
188 Bay State Rd	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
190 Bay State Rd	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
191 Bay State Rd	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
192 Bay State Rd	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
193 Bay State Rd	0	1	0			08/05/11						hazardous products	0	0	0	0	0	0	0	\$-	\$315.00	\$-
194 Bay State Rd	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
195 Bay State Rd	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
196 Bay State Rd	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
197 Bay State Rd	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
198 Bay State Rd	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
199 Bay State Rd	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
200 Bay State Rd	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
201 Bay State Rd	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
202 Bay State Rd	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
203 Bay State Rd	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-

Address	Fires Reported			Date Occurred			Cause			Number of Injuries that Required Treatment at a Medical Facility			Number of Fire-Related Deaths			Value of Property Damage						
	2010	2011	2012	2010	2011	2012	2010	2011	2012	2010	2011	2012	2010	2011	2012	2010	2011	2012				
204 Bay State Rd	0	0	0										0	0	0	0	0	0	\$-	\$-	\$-	
205 Bay State Rd	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
206 Bay State Rd	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
207 Bay State Rd	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
208 Bay State Rd	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
209 Bay State Rd	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
210-212 Bay State Rd	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
214 Bay State Rd	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
632 Beacon St	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
636 Beacon St	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
806-820 Beacon St	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
822 Beacon St	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
824-826 Beacon St	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
828 Beacon St	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
830 Beacon St	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
832 Beacon St	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
834 Beacon St	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
836 Beacon St	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
844 Beacon St	0	0	0										0	0	0	0	0	0	0	\$-	\$-	\$-
848 Beacon St	0	1	0										01/20/11							\$15.00	\$-	\$-
850 Beacon St	0	0	0																	\$-	\$-	\$-
852 Beacon St	1	0	0										09/21/10							\$300.00	\$-	\$-
856-862 Beacon St	0	1	1										05/06/11							\$-	n/a	\$1,000.00
864 Beacon St	0	0	0																	\$-	\$-	\$-
866 Beacon St	0	0	0																	\$-	\$-	\$-
870 Beacon St	0	0	0																	\$-	\$-	\$-
872 Beacon St	0	0	0																	\$-	\$-	\$-
906 Beacon St	0	0	0																	\$-	\$-	\$-
908 Beacon St	0	0	0																	\$-	\$-	\$-
1053 Beacon St	0	0	0																	\$-	\$-	\$-
10 Buick St	0	0	1										12/02/12							\$-	\$-	\$-
1 Buswell St	0	0	0																	\$-	\$-	\$-

Address	Fires Reported			Date Occurred			Cause			Number of Injuries that Required Treatment at a Medical Facility			Number of Fire-Related Deaths			Value of Property Damage		
	2010	2011	2012	2010	2011	2012	2010	2011	2012	2010	2011	2012	2010	2011	2012	2010	2011	2012
1-A Buswell St	0	0	0													\$-	\$-	\$-
2 Buswell St	1	0	0	09/07/10			cooking									\$300.00	\$-	\$-
3 Buswell St	0	0	0													\$-	\$-	\$-
5 Buswell St	0	0	0													\$-	\$-	\$-
6 Buswell St	0	0	0													\$-	\$-	\$-
7 Buswell St	0	0	0													\$-	\$-	\$-
10-18 Buswell St	0	0	0													\$-	\$-	\$-
11 Buswell St	0	0	0													\$-	\$-	\$-
15 Buswell St	0	0	0													\$-	\$-	\$-
17 Buswell St	0	0	0													\$-	\$-	\$-
22 Buswell St	0	0	1			10/07/12				cooking						\$-	\$-	\$-
24 Buswell St	0	0	0													\$-	\$-	\$-
29 Buswell St	0	0	0													\$-	\$-	\$-
31 Buswell St	0	0	0													\$-	\$-	\$-
33 Buswell St	0	0	0													\$-	\$-	\$-
34 Buswell St	0	0	0													\$-	\$-	\$-
35 Buswell St	0	0	0													\$-	\$-	\$-
37 Buswell St	0	1	0			02/27/11				cooking						\$165.00	\$-	\$-
38 Buswell St	0	0	0													\$-	\$-	\$-
39 Buswell St	0	0	0													\$-	\$-	\$-
40 Buswell St	0	0	0													\$-	\$-	\$-
41 Buswell St	0	0	0													\$-	\$-	\$-
42 Buswell St	0	0	0													\$-	\$-	\$-
43 Buswell St	0	0	0													\$-	\$-	\$-
44 Buswell St	0	0	0													\$-	\$-	\$-
45 Buswell St	0	0	0													\$-	\$-	\$-
47 Buswell St	0	0	0													\$-	\$-	\$-
48 Buswell St	0	0	0													\$-	\$-	\$-
50-52 Buswell St	0	0	0													\$-	\$-	\$-
55 Buswell St	0	0	0													\$-	\$-	\$-
575 Commonwealth Ave	0	0	0													\$-	\$-	\$-

Address	Fires Reported			Date Occurred			Cause			Number of Injuries that Required Treatment at a Medical Facility			Number of Fire-Related Deaths			Value of Property Damage					
	2010	2011	2012	2010	2011	2012	2010	2011	2012	2010	2011	2012	2010	2011	2012	2010	2011	2012			
580 Commonwealth Ave	0	0	0										0	0	0	0	0	0	\$-	\$-	\$-
625 Commonwealth Ave	0	0	0										0	0	0	0	0	0	\$-	\$-	\$-
627 Commonwealth Ave	0	0	0										0	0	0	0	0	0	\$-	\$-	\$-
629 Commonwealth Ave	0	0	0										0	0	0	0	0	0	\$-	\$-	\$-
700 Commonwealth Ave	0	0	0										0	0	0	0	0	0	\$-	\$-	\$-
708 Commonwealth Ave	0	0	0										0	0	0	0	0	0	\$-	\$-	\$-
710 Commonwealth Ave	0	0	0										0	0	0	0	0	0	\$-	\$-	\$-
714 Commonwealth Ave	0	0	0										0	0	0	0	0	0	\$-	\$-	\$-
722 Commonwealth Ave	0	0	1			07/20/12							0	0	0	0	0	0	\$-	\$-	\$349.00
726 Commonwealth Ave	0	0	1			05/02/12							0	0	0	0	0	0	\$-	\$-	\$349.00
728 Commonwealth Ave	0	0	0										0	0	0	0	0	0	\$-	\$-	\$-
1019 Commonwealth Ave	0	0	0										0	0	0	0	0	0	\$-	\$-	\$-
53-57 Deerfield St	0	0	0										0	0	0	0	0	0	\$-	\$-	\$-
33 Harry Agganis Way	0	1	0			12/30/11							0	0	0	0	0	0	\$-	\$165.00	\$-
46 Mountfort St	1	0	1			11/06/10							0	0	0	0	0	0	\$300.00	\$-	\$349.00
96 Mountfort St	0	0	0										0	0	0	0	0	0	\$-	\$-	\$-
98 Mountfort St	0	0	0										0	0	0	0	0	0	\$-	\$-	\$-
100 Mountfort St	0	0	0										0	0	0	0	0	0	\$-	\$-	\$-
500-504 Park Dr	0	0	1			11/18/12							0	0	0	0	0	0	\$-	\$-	\$-
509 Park Dr	0	1	0			02/01/11							0	0	0	0	0	0	\$-	\$315.00	\$-
514-522 Park Dr	0	0	0										0	0	0	0	0	0	\$-	\$-	\$-
515 Park Dr	1	0	0			11/29/10							0	0	0	0	0	0	\$300.00	\$-	\$-
2 Raleigh St	0	0	0										0	0	0	0	0	0	\$-	\$-	\$-
85-87 St Mary's St	0	0	0										0	0	0	0	0	0	\$-	\$-	\$-
90 St Mary's St	0	0	0										0	0	0	0	0	0	\$-	\$-	\$-

BOSTON UNIVERSITY ON CAMPUS STUDENT HOUSING FIRE SAFETY SYSTEMS

Address	Sprinklered	Fire Alarm	Fire/Evacuation Drills Annually
	NS = Not Sprinkled S = A system is present	AD = Auto dial to fire dept & BUPD NA = No alarm	
273 Babcock St	S	AD	1
275 Babcock St	S	AD	1
277 Babcock St	S	AD	1
11 Bay State Rd	NS	AD	0
30 Bay State Rd	S	AD	1
56 Bay State Rd	S	AD	0
58 Bay State Rd	NS	AD	0
59 Bay State Rd	NS	AD	0
60 Bay State Rd	S	AD	0
61 Bay State Rd	S	AD	0
62 Bay State Rd	S	AD	0
65 Bay State Rd	NS	AD	0
68 Bay State Rd	S	AD	0
69 Bay State Rd	NS	AD	0
70 Bay State Rd	S	AD	0
71 Bay State Rd	NS	AD	0
74 Bay State Rd	S	AD	0
75 Bay State Rd	NS	AD	0
76 Bay State Rd	S	AD	0
77 Bay State Rd	S	AD	0
78 Bay State Rd	S	AD	0
79 Bay State Rd	S	AD	1
80 Bay State Rd	S	AD	0
81 Bay State Rd	S	AD	1
82 Bay State Rd	S	AD	0
83 Bay State Rd	S	AD	1
84 Bay State Rd	S	AD	0
86 Bay State Rd	S	AD	0
88 Bay State Rd	NS	AD	0
90 Bay State Rd	S	AD	1
91 Bay State Rd	S	AD	1
92 Bay State Rd	S	AD	0
94 Bay State Rd	S	AD	1
96 Bay State Rd	NS	AD	0
110 Bay State Rd	NS	AD	0
112 Bay State Rd	NS	AD	1
113 Bay State Rd	NS	AD	0
115 Bay State Rd	S	AD	1

All buildings have smoke detectors, evacuation plans posted, and fire extinguishers.

Address	Sprinklered	Fire Alarm	Fire/Evacuation Drills Annually
	NS = Not Sprinkled S = A system is present	AD = Auto dial to fire dept & BUPD NA = No alarm	
117 Bay State Rd	S	AD	0
124 Bay State Rd	NS	NA	0
131 Bay State Rd	S	AD	0
133 Bay State Rd	S	AD	1
135 Bay State Rd	S	AD	1
139 Bay State Rd	S	AD	0
140 Bay State Rd	S	AD	1
153 Bay State Rd	S	AD	1
157 Bay State Rd	S	AD	0
158 Bay State Rd	S	AD	1
159 Bay State Rd	S	AD	1
160 Bay State Rd	S	AD	1
161 Bay State Rd	S	AD	1
162 Bay State Rd	S	AD	1
163 Bay State Rd	S	AD	0
164 Bay State Rd	S	AD	1
166 Bay State Rd	S	AD	1
167 Bay State Rd	S	AD	0
168 Bay State Rd	S	AD	1
169 Bay State Rd	S	AD	1
171 Bay State Rd	S	AD	1
172 Bay State Rd	S	AD	0
173 Bay State Rd	S	AD	0
175 Bay State Rd	S	AD	0
176 Bay State Rd	S	AD	1
177 Bay State Rd	S	AD	0
178 Bay State Rd	S	AD	0
179 Bay State Rd	S	AD	0
180 Bay State Rd	S	AD	1
181 Bay State Rd	S	AD	1
182 Bay State Rd	S	AD	0
183 Bay State Rd	NS	AD	0
179 Bay State Rd	S	AD	0
179 Bay State Rd	S	AD	0
188 Bay State Rd	S	AD	1
190 Bay State Rd	S	AD	1
191 Bay State Rd	NS	AD	1
192 Bay State Rd	NS	AD	1
193 Bay State Rd	S	AD	1
194 Bay State Rd	NS	AD	0
195 Bay State Rd	S	AD	0

All buildings have smoke detectors, evacuation plans posted, and fire extinguishers.

Address	Sprinklered	Fire Alarm	Fire/Evacuation Drills Annually
	NS = Not Sprinkled S = A system is present	AD = Auto dial to fire dept & BUPD NA = No alarm	
196 Bay State Rd	S	AD	0
197 Bay State Rd	S	AD	0
198 Bay State Rd	NS	AD	0
199 Bay State Rd	S	AD	0
200 Bay State Rd	S	AD	0
201 Bay State Rd	S	AD	0
202 Bay State Rd	S	AD	0
203 Bay State Rd	S	AD	0
204 Bay State Rd	S	AD	0
205 Bay State Rd	NS	AD	0
206 Bay State Rd	S	AD	0
207 Bay State Rd	S	AD	0
208 Bay State Rd	S	AD	0
209 Bay State Rd	S	AD	1
210-212 Bay State Rd	S	AD	0
214 Bay State Rd	S	AD	0
632 Beacon St	S	AD	1
636 Beacon St	NS	NA	0
806-820 Beacon St	S	AD	0
822 Beacon St	S	AD	0
824-826 Beacon St	S	AD	0
828 Beacon St	S	AD	0
830 Beacon St	S	AD	0
832 Beacon St	S	AD	0
834 Beacon St	S	AD	0
836 Beacon St	S	AD	0
844 Beacon St	S	AD	0
848 Beacon St	NS	AD	0
850 Beacon St	NS	AD	0
852 Beacon St	S	AD	0
856-862 Beacon St	S	AD	0
864 Beacon St	S	AD	0
866 Beacon St	NS	AD	0
870 Beacon St	S	AD	0
872 Beacon St	S	AD	0
906 Beacon St	S	AD	0
908 Beacon St	S	AD	0
1053 Beacon St	S	AD	1
10 Buick St	S	AD	1
1 Buswell St	S	AD	1
1-A Buswell St	S	AD	0

All buildings have smoke detectors, evacuation plans posted, and fire extinguishers.

Address	Sprinklered	Fire Alarm	Fire/Evacuation Drills Annually
	NS = Not Sprinkled S = A system is present	AD = Auto dial to fire dept & BUPD NA = No alarm	
2 Buswell St	S	AD	0
3 Buswell St	S	AD	0
5 Buswell St	S	AD	1
6 Buswell St	S	AD	0
7 Buswell St	S	AD	0
10-18 Buswell St	S	AD	0
11 Buswell St	S	AD	0
15 Buswell St	S	AD	1
17 Buswell St	S	AD	0
22 Buswell St	S	AD	1
24 Buswell St	S	AD	1
29 Buswell St	S	AD	0
31 Buswell St	S	AD	1
33 Buswell St	S	AD	0
34 Buswell St	S	AD	1
35 Buswell St	S	AD	0
37 Buswell St	S	AD	1
38 Buswell St	S	AD	0
39 Buswell St	S	AD	1
40 Buswell St	S	AD	0
41 Buswell St	S	AD	0
42 Buswell St	S	AD	0
43 Buswell St	S	AD	1
44 Buswell St	S	AD	0
45 Buswell St	S	AD	0
47 Buswell St	S	AD	0
48 Buswell St	S	AD	1
50-52 Buswell St	S	AD	0
55 Buswell St	S	AD	0
575 Commonwealth Ave	S	AD	1
580 Commonwealth Ave	S	AD	0
625 Commonwealth Ave	NS	AD	0
627 Commonwealth Ave	NS	AD	0
629 Commonwealth Ave	NS	AD	0
700 Commonwealth Ave	S	AD	1
708 Commonwealth Ave	NS	AD	0
710 Commonwealth Ave	NS	AD	0
714 Commonwealth Ave	NS	AD	0
722 Commonwealth Ave	S	AD	0
726 Commonwealth Ave	S	AD	0
728 Commonwealth Ave	S	AD	0

All buildings have smoke detectors, evacuation plans posted, and fire extinguishers.

Address	Sprinklered	Fire Alarm	Fire/Evacuation Drills Annually
	NS = Not Sprinkled S = A system is present	AD = Auto dial to fire dept & BUPD NA = No alarm	
1019 Commonwealth Ave	S	AD	1
53-57 Deerfield St	S	AD	0
33 Harry Agganis Way	S	AD	1
46 Mountfort St	S	AD	0
96 Mountfort St	S	AD	1
98 Mountfort St	S	AD	1
100 Mountfort St	S	AD	1
500-504 Park Dr	NS	AD	0
509 Park Dr	NS	AD	1
514-522 Park Dr	S	AD	0
515 Park Dr	NS	AD	0
2 Raleigh St	S	AD	0
85-87 St Mary's St	S	AD	0
90 St Mary's St	NS	AD	0
37-47 St Mary's St*	NS	AD	0
457 Park Drive*	S	AD	0
455 Park Drive*	S	AD	0
19 Euston St*	S	AD	0
7 Euston St*	S	AD	0
483 Commonwealth Ave*	S	AD	0
481 Commonwealth Ave*	S	AD	0
146 Commonwealth Ave*	S	AD	0
141 Carlton St*	S	AD	1
37-39 Carlton St*	S	AD	1
875 Beacon St*	NS	AD	0
867 Beacon St*	NS	AD	0
855 Beacon St*	S	AD	0
853 Beacon St*	S	AD	0
845 Beacon St*	S	AD	0
531 Beacon St*	S	AD	1
521 Beacon St*	S	AD	0
519 Beacon St*	S	AD	0
517 Beacon St*	S	AD	0
512 Beacon St*	S	AD	1
815 Albany St**	S	AD	0

*Non-campus residence

**Boston University Medical Campus address.

All buildings have smoke detectors, evacuation plans posted, and fire extinguishers.