

**NEIDL Agent Incident Reporting Summary July 2017 - September 2017, Q3**

Date of Incident	Incident Type / Agent Involved	BSL	Transmissible Person to Person	Description	Reportable Incident	Reportable of Clinical Illness	Comments / Corrective Actions
8/23/17	Skin exposure to splash of Sodium Hydroxide	N/A	No	A mechanic and two contractors were exposed to a splash of sodium hydroxide when doing monthly preventative maintenance. There was no exposure to the waste water tank, its contents or to biological hazards.	No	No	<p>PPE within this room will be increased to have a chemical resistant apron, extended gloves, safety goggles, and a face-shield available while working with caustic or acidic material.</p> <p>An outer hose was placed on top of the discharge hose as a means of double containment, so that if this were to reoccur, the liquid would drip down onto the barrel and remain contained instead of compromising the surrounding area.</p>